

\*\*REMEMBER – IF TOUCH CALIBRATION IS REQUIRED, YOU ARE ADVISED TO PRESS THE RIGHT END SIDE OF THE EACH BUTTON.

## 1. Select 'SETUP'



2. Select Touch Screen.



Press on the Center of the target. Repeat as it moves around the screen.

3. It will bring up Calibration screen mode.

The cross cursor will move counter clock wise, and every time it stops on corner, Gently touch it on center of the cross, and it will move to next corner.

Once all is done, It will save automatically.

And all you need to do is launch Navigation from the main menu.